

Jesday, 15/07/2008 10:07:05 AM **Melanie Fauteux**

Process Sheet

omer: CU-DAR001 Dart Helicopters Services

Drawing Name: BASE ASSEMBLY

Number: 40506

Part Number: PB674300147

(umber:



Seq. #:

Machine Or Operation:

Description:

6.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP



7.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

8.0

PACKAGING 1

PACKAGING RESOURCE #1






Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: L

FINAL INSPECTION/W/O RELEASE




9.0



Comment: FINAL INSPECTION/W/O RELEASE





Job Completion





Tuesday, 15/07/2008 10:07:05 AM Melanie Fauteux **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : BASE ASSEMBLY Job Number : 40506-1 **Estimate Number** : 13419 P.O. Number Part Number : PB674300147 --This Issue : 15/07/2008 S.O. No. : **Drawing Number** · B6743001 P.15 Prsht Rev. : N/A Project Number First Issue : 15/07/2008 Type : LARGE FAB ASSY : B1 **Drawing Revision** Previous Run Material Written By **Due Date** : 22/07/2008 Checked & Approved By Comment : Est Rev:A 08-06-25 new issue DD verified by:ec **Additional Product** Job Number: Seq. #: Machine Or Operation: Description: 1.0 D344011 Gusset Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) 39959 08.07.16(3 2.0 Square Tube Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Square Tube 3 4060 3.0 PB6743001141 Square Tube Comment: Qty.: 2.0000 Each(s)/Unit Total: 10.0000 Each(s) Square Tube 3 4060 3 4.0 Square Tube Comment: Qty.: 1.0000 Each(s)/Unit Total: 5.0000 Each(s) Square Tube 3 40601 5.0 LARGE FAB LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1- weld as per dwg B67-43001 using jig PB67-43001-315 Hook Qty (3) Batch: 324020 = 14

Page 1

Form: rprocess